

**Subject / Vehicles:**

526 Eccles Ave.  
South San Francisco, CA

## Cam Timing Marks - Legend & Chetak

There has been some confusion about setting the cam timing correctly due to misalignment of the Cam Timing Mark cast into the cylinder head.

The picture below shows the correct alignment of the cam sprocket in relation to the cast-in timing mark on the cylinder head when the piston is at Top Dead Center.

Details of engine assembly and timing chain installation are discussed in the Service Manuals.

If working with the timing chain, be sure to read the January 15th Tech Note concerning the correct installation of the Cam Chain Tensioner.

